SOUTH PRODUCTION NOTES

Feb 9, 2016 11-7 Shift Notes

BASF EMPLOYEES

72 Last Recordable 140 Last Lost time

SAFETY Notes: Check the walkways for ice and treat with icemelt. Need to remind operators that Styrene material on line #2 can't be washed down the drain. Building 31 sump currently shut off. We had a false alarm on the fire system in bldg 16. System status is currently displaying "not normal" – WOW.

Title V Notes: <u>Trimer</u> –tank 2 ORP probes were worked on Friday – keep an eye on them. The chem tank ORP probe still isn't reading correctly.

<u>CTO</u> – CTO is running but the valve still needs to be fixed. Keep an eye on the system. #3 is currently running to CTO.

<u>F-1 Scrubber</u> – Continue sampling of scrubber and sump in building 31. Sump was sent to WWTP on afternoon shift.

#1 MED / D 1780: Priority #1

We are not going to run until the load cell is fixed. Possibly this week. We are switching #3 line to D1780. This is a very high priority as it is going to be supplying the Old Pfaudler and #6 calciner.

When we start do not increase the speed on the extruder to above 60 hz until IMC can correct the issue. Still need low level probe on miners installed.

#1 RC / D 1780:

Done feeding until we get some more material. Feed in batch order and fill out calciner feed sheets.

#2 MED line / Styrene: Priority #2

Maintenance fixed the oscillator belt on day shift. Justin will be available Tuesday morning to start the line back up.

There are drums of wet mix. There are also several drums of material that will need to be refed through the dryer – do not feed this material until instructed to. Need to remind operators that Styrene material can't be washed down the drain. The new mixer plows should be in the week of the 2/29.

#2 RC/ Styrene:

Continue with refiring lots 4 and 5. We found 3 bags of material on the first floor that need to be fed.

Continue to keep an eye on the liners in the bags; have had few instances where it falls in. The Floor CRT will need to take a sample out of the F1 scrubber and the sump in building 31 to wastewater. Before unlocking building 31 sump WWTP will test these samples for moly and if the sump is low, we can unlock and send to WWTP. At all other times the west sump will remain locked out.

Need to remind operators that Styrene material can't be washed down the drain. The new mixer plows should be in the week of the 2/29.

#3 MED line / D-1780 next

Gem could not get the rebuilt mixer discharge valve to seat properly. They stopped working at about 8pm and will be back in the morning to continue. Make sure we are greasing end seals.

Please keep a close eye on the ammonia and nitric additions.

#3 RC / AL-3945:

Out of feed. When we restart we will begin with Lot 191; SS#1 is currently hanging.

Feed in batch order and fill out calciner feed sheets.

#4 RC / D-0222 Cleaning:

We need to refeed/remake the first 3 bags. Run out hopper and purge calciner then drop temps 20 deg and refeed the first 3 bags to the calciner. Just finished SS#4 and are filling remake SS#1.

Screens changed out on day shift to a 7mesh and a special 14mesh fines. Keep an eye on the samples and amount of fines coming off the calciner.

We will need to remake and resample the bags.

We still need fish labels - may be in Calvins area in the stores.

We will take the 1st ½ drum and haz-waste due to possible contamination.

#5 RC / Catoxid:

Continue feeding.

We will need to look at the DC every hour for the readings sheet.

DC gauges are working at the dust collectors. For some reason the control room screens are not reading correctly. Kirk has been notified.

Do NOT fill hopper all the way up due to blowdowns turning on and overflowing the hopper. It should not be filled past 2ish feet below the top to allow room for blowdowns.

2 bags of wet material to wait for engineering - don't feed now.

Continue to monitor 5A after filter. The log sheet is in the 2nd floor MCC room bldg. 11 - needs to be filled out every 2 hrs.

#6 RC & Dryer / D-0761:

Need a label made for the final partial drum. Last two pallets of material are by the Abbe. Fines drum is weighed and labeled.

Cleanup sheet is by calciner, screener needs to be changed over.

There is a check weigh scale located in the middle of building 27. Please check weigh all drums.

West Pfaudler / D- 0222:

Tank 7 is complete and we can start a batch.

Only lot 187/188 is OK to use. Do not use any other lots.

Keep an eye on tank 7, See email about using the auto steam valve working on one of the stations in the control room.

Al 3945 Lot 187 and 188 are in pass.

East Pfaudler/ D-0761:

Started clean up. Need MOD to finish cleaning.

6 Tank: Tank empty

Valve fixed. There was a screen and band clamp in the valve.

7 Tank: D-0222 Solution

Batch is complete.

Maintain tank at 50 deg. Will need to monitor and adjust steam. Auto valve is supposed to be working on the computer #868 only. See email on CRT desk

National Dryer / D-0222:

Continue to feed batches as material is available.

PK Blender / Catoxid:

Issues with the transfer pump have the PK shut down. WOW Level indicator is working on Chrome tank.

Need to make sure that the building is being cleaned up!

Make sure the dust collector and scrubber are within range before starting.

Dust collector can be blown down by switching the magnahelic gauge to 0 and then shutting off the blower when it starts to blow down. We need to install another row of bags in the DC when able. DC gauge has been added to Wonderware and has been moved over to near the weight tank. Gauge should be set at 3.5 and 4.25.

Abbe Blender / D 5206:

HF tote has been closed up and Abbe lid was remove and vessel cleaned out. Cover plates over open hole in floor have been reinstalled.

Tower 3 / Cu-0860:

Tower loaded.

Tower 6 / Cu-0860

Tower loaded.

North Screener /Cu-1155:

Screener is set up for Cu-1155.

South Screener /Cu 0860:

South Screener is set up for 0860. Did some testing on Friday and it will need some work before starting.

#2662 (west) Pill Machine /

Back together and holding.

#2664 (east) Pill Machine /

Back together and holding.

TK #2 / Zr-0404:

Continue loading and unloading.

When we are done feeding the current lot we will stop feeding until more pills can be made.

TK #4 / Cu-2508:

Kiln was cleaned and set up for Cu-2508. We will be getting an MOD for this product and we need to get it lit Tuesday. Continue to rework Cu-2508 drums per Mark's email. Need to repack drums into 120 bags (drums have been brought to repack hopper).

Need to inspect area before calling EHS to inspect.

Harrop Kiln / Al-4196:

Waiting on parts for the regulators. Eliott may need to finish the burner tuning. Saggers have been switched out and are ready for next run.

Building 27 Belt Filter / Cu-6081:

DL Page completed their work on the dryer chamber. Holding for more material/start up orders. We have switched to 188 lined super sacks. These will need cardboard sleeves around them.